

Teemi TMCT-07 Wireless Barcode Scanner

Pairing and Program Chart

Pairing Instructions (if necessary)



Programming Chart

1 
Enter Setup

2 
Factory Reset

3 
Do not Apply Enter for suffix

4 
Apply Tab for suffix

5 
Do Not Transmit UPC-A Checksum

6 
Do Not Transmit UPC-E Checksum

7 
Exit with Save